Aluminum PC Case Installation Guide

Case components:


Multi-media port
Patented tool-less 5.25” device mounting
120mm fans
Patented tool-less PCI add-on card holder
Patented tool-less PSU mounting bracket

Hardware list

* Extra quantities are spare parts.

Screw (12) to fix drive & motherboard	Buzzer(1)	Thumb screw(28) for HDD	Shorter vision thumb screw(6) for mother board mount
Bracket(1) for power supply mounting	PCI bracket (1)	Screw (4) for PSU mounting	Longer vision thumb screw(3) for mother board mount
Box(1) for spare parts	Cable tie (2) for cable	USB3.0 to USB2.0 convertor (1)	SATA cable(2) for HDD

Side panels installation

Loose the screw and pull the latch to release the side panel.



Remove the side panel.



Adding a lock to secure the hardware.

Fan adjustable device



3.5" Hard disk installation

Loose thumb screws to remove the HDD cage.



Insert HDD, secured with thumb screws.

Insert the HDD cage to the mounting position.



Fasten the thumb screw to secure the HDD cage.

I/O port installation





HD AUDIO



SATA



PCI bracket installation



For access to rear I/O port.

USB3.0 to USB2.0 convertor



Motherboard installation



Secure the stand-off on the M/B tray which match with the M/B fix points, place the M/B on the stand-off fasten with the thumb screws to secure.

PCI Add-on card installation



Open the aluminum latch to remove the PCI slot bracket.



Push the card into the PCI slot, close the aluminum latch to secure the card.

ODD installation



1. Remove the 5.25" to 3.5" converter.



2. Remove the 5.25" ODD bezel.



3. Slide the 5.25" ODD bezel downwards to remove it.



4. By pressing plastic handle to release the mounting bracket.

5. Push the CD-ROM into the ODD cage module, close the bracket to secure.
6. Reverse previous steps for installation bezel & converter.



If you wish to use the 5.25" ODD bezel, please adjust the metal pin position on the mounting bracket



Adding the rubber pad to ODD's eject bottom, when 5.25" ODD bezel couldn't reach to the ODD.

PSU tray installation



Loosing four thumb screws to remove the PSU mounting bracket.



Assembling the power supply with PSU mounting bracket, and push in gently.



Fasten four thumb screws onto the case to secure.



Remove the HDD cage for long PSU.

PSU installation



Place the PSU on the stand, and push again the rear panel.



Place the PSU bracket into according slot as shown.



Lock the PSU bracket to secure the PSU.
* For transportation, please place screw to secure the PSU

Vents for water cooling

Place the water tube through the rabber cover.

Removable upper double fan module



Loosing screws to remove fan module.



Follow the arrow to remove the filter, press the plastic clips to release the washable air filter.